John Richardson House Richardson Park, Delaware HABS No. Del-45

HAES DEL.

2 - RICHT

.

PHOTOGRAPHS
WPITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Delaware

ADDENDUM FOLLOWS...

Mistoric American duildings Survey Weston H. Blake, District Officer 909 West Street, Wilmington, Deluvere

HABS DEL.

2. RICHP

1 -

## JOHN RICHARDSON HOUSE Richardson Park, New Castle County, Delaware

Owner:

A. J. Beste

Date of Erection:

About 1723

Present Condition:

Fair

Number of Stories: basement kitchen. Two and one half with

Materials of Construction: Brick walls; wood framong; original shingle roof covered with asbestos shingles.

Other Existing Records: Scharf's History of Delaware, Vol.2, P.881; Conrad's History of Delaware, Vol.2, P.461; Offices of Recorder of Deeds and Register of Wills of New Castle County.

Additional Data: The exact date of erection cannot definitely be established, nor the builder, but it is believed to have been built by John Richardson in the year mentioned above. An unusually fine example of early 18th Century brickwork with the usual Flemish Bond with glazed headers on the main facade. In plan there are two small rooms on each of the first and second floors, with winding enclosed staircase adjacent to fireplace in the east room. There is a basement kitchen opening to the grade on the north side. Note the projecting brick courses in the gable end and chimney placed off center of the ridge, to allow room for a small window in the attic space.

Nastrict Officer.

fco. fan 21 37 40

## Addendum to:

John Richardson House (Brick Mill House) (Glynrich)
Maryland Avenue (Route 4) and Race Street
Wilmington Vicinity
New Castle County
Delaware

Building is in same location but has a new address:

15 Race Street Richardson Park New Castle County Delaware HABS No. DE-45

HABS DEL, 2-RICHP, 1-

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Addendum to 1 data page previously transmitted to the Form 10-920 Library of Congress. UNITED STATES DEPARTMENT OF THE INTERIOR (Aim 1983)

JOHN RICHARDSON HOUSE (Brick Mill House) (Glynrich) HABS No. DE-45 (Page 2) HABS

## **ARCHITECTURAL DATA FORM**

DEL. 2-RICHP COUNTY STATE TOWN OR VICINITY 1-Christiana Bundred Wilmington Vicinity Delaware New Castle HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) HABS NO. (Scharf, History of Delaware, 1888) DE-45 Addendum to: John Richardson House SECONDARY OR COMMON NAMES OF STRUCTURE Brick Mill House; Glynrich COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Originally recorded as: Maryland Avenue (Route 4) at Race Street; Building is in the same location but has assumed a new address: 15 Race Street, Richardson Park, New Castle County, Delaware DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE) 1723 attributed, architectural evidence suggests ca. 1735. SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Richardson House is one of the best preserved examples of early 18th-century domestic architecture extant in Delaware. The building retains numerous interior and exterior details which are extremely rare. STYLE (IF APPROPRIATE) vernacular miller's house. MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Brick (glazed header flemish bond south elevation, stuccoed east elevation, mixed common bond north and west elevations); rubble stone foundation: common rafter roof (possibly 18th-century replacement). SHAPE AND DIMENSIDNS OF STRUCTURE *(SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)* Originally three-bay, hall-parlor plan two stories in elevation with a banked cellar kitchen and unfinished attic (see attached field notes). EXTERIOR FEATURES OF NOTE Glazed header flemish bond primary elevation; tabled six-panel door in champfered and flare stopped architrave with four-light transom defines primary entry; segmental arched window openings on primary elevation and rowlock arched openings on secondary elevations; replaced sash. INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Hall: paneled fireplace wall with beavily molded mantel cornice, two-panel cupboard and stair to cellar door are original. Parlor: original stair box with vertical board walling (beaded edge) and two-panel doors bung on foliated HL hinges. Parlor-chamber: mantel cornice and MAJOR ALTERATIONS AND ADDITIONS WITH DATES (CORE. From above) beaded board closet. Sash replaced 19th and 20th centuries; original beaded board partition wall removed from between first floor rooms and reused to subdivide second floor; 20th century north shed addition replaces earlier one of similar appearance. PRESENT CONDITION AND USE In the process of rehabilitation for use as light commercial space. OTHER INFORMATION AS APPROPRIATE Two additional features of note: 1. Cellar kitchen hearth intact with wrought crane and bakeoven opening, 2. Two examples of fixed or casement window architraves (attic landing and cellar north wall) with rabbeted insets for iron frame and evidence of stiffening bars (see fieldnotes). SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)

COMPILER, AFFILIATION Bernard Herman, Center for Historic Architecture and Engineering, University of Delaware

J. Thomas Scharf, History of Delaware (Philadelphia, 1888)

National Register of Ristoric Places

DATE 2-9-85